

## INFORMAZIONI SULL'ORDINE

Descrizione		Numero d'ordine
<b>POLI 5-gas detector Diffusione</b>		M004-0028-W00
LEL 1 - 100%	O <sub>2</sub> 0.1 - 30 % vol	
CO / H <sub>2</sub> S 0 - 500ppm / 0.1 - 200 ppm	SO <sub>2</sub> 0.1 - 20 ppm	
<b>POLI 4-gas detector Diffusione</b>		M004-0001-W00
LEL 1 - 100%	O <sub>2</sub> 0.1 - 30 % vol	
H <sub>2</sub> S 0 - 100 ppm	CO 0 - 1000 ppm	
<b>POLI 4-gas detector Diffusione</b>		M004-0027-W00
LEL 1 - 100%	O <sub>2</sub> 0.1 - 30% vol	
H <sub>2</sub> S 0.1 - 100 ppm	CO 1 - 1000 ppm	
<b>Rivelatore POLI a 3 gas Diffusione</b>		M004-0002-W00
LEL 0 - 100%	O <sub>2</sub> 0.1 - 30 % vol	
H <sub>2</sub> S 0 - 100 ppm		
<b>POLI 2-gas detector Diffusione</b>		M004-0003-W00
LEL 0 - 100%	O <sub>2</sub> 0.1 - 30 % vol	
<b>Rivelatore di gas singolo POLI</b>		M004-0009-W00
LEL 0 - 100%		
<b>POLI Pompato UL LEL / O<sub>2</sub> / H<sub>2</sub>S / CO Kit spazio limitato</b>		M004-0040-W00
<b>Rilevatore POLI a 4 gas pompato</b>		MPA1-21A601-W2040
LEL 0 - 100%	O <sub>2</sub> 0.1 - 30 % vol	
CO 0 - 1000 ppm	H <sub>2</sub> S 0 - 100 ppm	
<b>Rilevatore POLI a 5 gas pompato</b>		MPA1-21A1A6-W10L0
PID 0.1 - 2000 ppm	LEL 0 - 100%	
O <sub>2</sub> 0.1 - 30 % vol	CO 0 - 1000 ppm	
H <sub>2</sub> S 0 - 100 ppm		
<b>Rilevatore POLI a 5 gas pompato</b>		MPA1-21A3A6-W10L0
NDIR CO <sub>2</sub> 0-50.000ppm	LEL 0 - 100%	
O <sub>2</sub> 0.1 - 30 % vol	CO 0 - 1000 ppm	
H <sub>2</sub> S 0 - 100 ppm		
<b>WatchGas POLI POLI Pompato (LEL / O<sub>2</sub> / H<sub>2</sub>S / CO) Soldato senza fili</b>		MPAS-21A601-02040