

SST1A Firmware V70 – Toxic

Changes

- Improved temperature compensation for H2 Low
- Improved factory calibration settings for PH3